TB 96



STANNAH LIFTS LTD

TECHNICAL BULLETIN

INSTALLATION			MAINTENANCE ISSUE
For the Attention of :		Service Engineers, Installers, Trade Customers, Testers, Training Dept, H & S Manager etc	
Date :	19-03-2010		
Product :	MRLi Lifts using GEV valve assemblies and Pawl Device.		
Subject :	Modification to power supply wiring.		
Pages :			
Originator :	Stannah Lifts Ltd, Anton Mill, Andover, Hants SP10 2NX 01264 339090		

Overview

As a result of introducing the Pawl device and Blain Valve to MRLi lifts it has been found that the power required to energise the VMD hydraulic valve is sometimes insufficient. This, in the majority if instances, becomes apparent during testing before handover, but may also present itself whilst the lift is in service. The symptoms are that the lift does not lower with full load in the car.

Details

To overcome this issue a simple and straightforward modification can be undertaken.

Notes:-

The modification is to change the feed to the valves from VM+ to C+ as shown overleaf.

Action Required

Factory :- All Lifts produced from March 22nd 2010 will be modified by the factory.


Installation Test :- All lifts handed over from receipt of this bulletin are to have the modification carried out.

<u>Service</u>:- All lifts found to have operational problems should have the modification carried out.

No parts are required other than a short length of single core cable.



DELTA





STAR/DELTA

