

**TB155**

## **SAFETY BULLETIN**

**INFORMATION ONLY**

---

**For the Attention of :** Kim Saville, Jo Walsh, Mark Perry, Surveyors, Installers

**From:** Jo Walsh

**Date :** 20<sup>th</sup> August 2015

**Subject :** Incident Report 1088

**Product:** Platform Lifts – Midi Lift SL

**Pages :** 1

---

### **Background**

Norwich Service Branch attended site on the 6/3/15 – He noticed, “the lift door operator has a ‘nip’ point on mechanical operation in the open position”. Mark Freeman has spoken to Lifts Ltd (Nick Powell) who advised, “the operator arm is fitted incorrectly. The arm should be fixed to the slam over to the left four fixing holes, which would then remove the nip point being created”.





# Stannah

**Actions:**

Door closers to be fitted on site as per installation manual.