

**TB154**

## **SAFETY BULLETIN**

**INFORMATION ONLY**

---

**For the Attention of :** Kim Saville, Jo Walsh, Mark Perry, Surveyors, Installers

**From:** Jo Walsh

**Date :** 20<sup>th</sup> August 2015

**Subject :** Incident Report 1066

**Product:** Platform Lifts – Lehner Stair riser CR

**Pages :** 1

---

### **Background**

Brackley Service Branch attended on 1/12/14 – “Engineer attended on 1<sup>st</sup> service visit. Found the over travel limit switch had failed. The switch could not be made in the event of over travel failure as it would have made contact the wall and floor before it could ever have made the switch. Incorrectly installed/not tested. Adjustments/corrections made by Engineer”.





# Stannah

**Actions:**

The ultimate limit has to be adjusted on site to suit the site conditions by the installer.