

TB-TKE005

TECHNICAL BULLETIN

SAFETY ISSUE

For the Attention of : Branch Managers, Graham Mears, Paul Ayers, Peter Amura, Pete Canning, Paul Clifton, Phil Beresford, Darren Cooper, Mike Wells, Craig Mellor

From: Angelos Strantzalis – Senior Product Support Engineer

Date : 12 Mar 2015

Product : TKE

Subject : **Cutting of Synergy CWGHT Guides**

Pages : 85 including the 3 documents (2 PDF & 1 Word) from TKE France

Background

Please find attached from TKE, their formal Technical Advice Memo concerning the above topic.

We have checked with Mike Wells, who has advised the following:

- There appears to be no immediate action required unless there is a problem with subsidence.
- I recommend we issue a TB in the usual way using the information provided in the Word document which is straight forward and could be carried out during a service visit.

Detail

See list below of the 29 units.

| | |
|---------|----------|
| 88534 | ST320101 |
| 88535 | ST320102 |
| 88530 | ST320179 |
| M257093 | 30075263 |
| M257093 | 30075264 |
| 85085 | ST310245 |
| 85321 | ST310289 |
| 85322 | ST310290 |
| 85435 | ST310017 |
| 85092 | ST310231 |
| 85091 | ST310232 |
| 84931 | ST310262 |
| 81555 | ST310065 |
| 85434 | ST310016 |
| M248781 | 10120096 |

| | |
|-------|----------|
| 85069 | ST310266 |
| 85442 | ST320007 |
| 85502 | ST320012 |
| 82125 | ST310106 |
| 82763 | ST310131 |
| 87202 | ST320114 |
| 87203 | ST320115 |
| 87204 | ST320116 |
| 87205 | ST320117 |
| 86063 | ST320050 |
| 81563 | ST310090 |
| 81562 | ST310089 |
| 80897 | ST310033 |
| 80896 | ST310034 |

If you have any questions concerning this Bulletin please speak with **Mike Wells** on **07836 272233**