

TECHNICAL BULLETIN

For the Attention of : Service Engineers

Date : 28.01.08

Product : Stairiser SX, external model

Subject : Rusting

Status : Service monitor

Pages : 1

Originator : Stannah Lifts Ltd, Anton Mill, Andover, Hants SP10 2NX 01264 339090

Summary

3 components located on Stairiser SX external units manufactured before July 2007, have been found to suffer rusting due to an incomplete coating process. It is considered prudent that these components should be inspected & monitored in the field during service.

Detail

It is requested that the following 3 components are inspected & monitored for signs of excessive rusting in line with normal inspection practice. If it is considered that the integrity of any component has been affected, the component shall be replaced & sent back in accordance with the component warranty returns procedure.

The service routine should include an application of light grease to the affected components.

