

LIFT TYPE:- System 21 Lifts - Ram straps.

To: Stannah Services
Trade Customers.
Installers
Testers

Description

We have recently experienced a problem with the lack of support between the base of the piston and the top of the piston stump, for indirect acting lifts.

Action

All system 21 lifts installed from May 2002 should be checked at the next service visit for adequate support.

The piston and stump should be supported at approx. 300mm either side of the stump/cylinder joint.

Any pistons or stump found to be not adequately supported are to have the appropriate support bracketry fitted which is available from Andover.

