

TECHNICAL BULLETIN

For the Attention of : Installers, H & S Manager, Installations, CDO, Production

Date : 15/05/07

Product : System 21 Passenger lifts

Subject : Structure Support Member

Status : Urgent Safety Issue

Pages : 1 of 1

Originator : Stannah Lifts Ltd, Anton Mill, Andover, Hants SP10 2NX 01264 339090

Detail

Please could you check that the Support Member Welded Assembly used across structure ring sections to support scaffold boards are of the correct length.

It has come to light that 900 entrance Structure Supported MRLi contracts may have been supplied with the incorrect length which must be replaced with the correct size for that structure.

In general please check that you have the correct length of Support Member on all Structure Supported jobs. Do not attempt to use an incorrect length. Get it replaced immediately.

Please inform Mick Mais at Stannah Lifts if this is the case.

