

TB 177 revision A

TECHNICAL BULLETIN

SAFETY ISSUE


For the Attention of : Trade Customers, Installers, Installations Trainer, H&S Manager

Date : 28th February 2022

Product : Midilift Piccolo, SLplus & XLplus cabin lifts

Subject : M12 Guide Clips – UPDATE

Pages : 2



Originator : Stannah Lifts Ltd, Anton Mill, Andover, Hants SP10 2NX 01264 339090

Detail

This revision A bulletin provides an update to the original bulletin TB177 which advised that M12 guide clips marked $\frac{M2}{V}$ were not to be used until further notice.

We are pleased to advise that, following some design changes to the Midilift cabin products (larger diameter holes in all guide mounted brackets), these clips will be re-introduced on lifts manufactured on and after 28th February 2022. This means that any M12 clip supplied by Stannah (regardless of markings) will be able to be used on lifts made after this date.

In addition, the product installation manuals were updated on 20th April 2021 to include a torque setting for all guide clips as well as details of a visual check to confirm that the heel of the clip has made contact with the face of the bracket.

All future guide clips must be installed in accordance with the latest versions of the product installation guide. At time of writing, these are:

- Midilift SLplus Installation Guide - Issue 6 (dated 07/04/2021)
- Midilift XLplus Installation Guide - Issue 8 (dated 07/04/2021)
- Midilift Piccolo Installation Guide - Issue 8 (dated 07/04/2021)
- Installation Guide FX Structure Piccolo – Issue 3 (May 2021)

Latest copies are always available at www.stannahtechnical.co.uk

See summary on page 2 of this bulletin for details of the action required.

Summary

Action required:

- **Cabin lifts delivered before 17th March 2021 – continue to check clips on any cabin lifts in storage/work in progress and request M2U replacements if required (as per original version of TB177)**
- Cabin lifts delivered between 17th March 2021 and 28th Feb 2022 – M2U clips supplied (no action required)
- Cabin lifts manufactured from 28th Feb 2022 – brackets incorporate larger diameter holes so that any M12 clip supplied by Stannah can be used (no action required)

Please ensure that latest versions of the installation manuals are adhered to.