

TB 186

TECHNICAL BULLETIN

INFORMATION ONLY

For the Attention of : Service Engineers, Installers, Trade Customers, Lifts Spares
Date: June 10 2022
Product : Midilift: GL, SL, SLplus & XLplus
Subject : New manual door closer
Pages : 1

Originator : Stannah Lifts Ltd, Anton Mill, Andover, Hants SP10 2NX 01264 339090

Detail

From May 30 2022 door closer Ryobi model D-2550BC (Stannah part no 513352) replaces door closers Stannah part nos. 500127 (used on steel frame doors) & 500298 (used on fire doors). The new closer offers improved performance in terms of the balance between lower opening force, for ease of use, together with reliable closing force.

For new lift installations, the new closer simply substitutes the 'old' closers, & is supplied with the lift as previously organised. A kit of parts is also offered for the situation of retrofitting the old closer types, with the new version, should the need arise. For the latter, kit part number 6104110 (not 513352) should be ordered from Lift Spares.

In either instance of new or retrofit installation, the setting up procedure differs from previous practice; instructions for correct setup are provided with each closer. A critical point is that adjustment of the closer setting controls should be carried out only as described in relevant instruction document – this is important to achieve the optimum balance of opening & closing forces.

For reference, new closer instruction documents can also be found on [stannahtechnical](#) under *Midilift SL/Midilift Installation Information*.

Summary

Door closer part number 513352 has replaced two different previously used closer types. The new closer offers improved balance of opening & closing forces. It is important to apply closer setting adjustments only as described in the instructions supplied with each closer.