

## SAFETY BULLETIN

---

**For the Attention of :** Installers, Lifts Services, Trade Customers

**Date :** 19/11/07

**Product :** System 21 Passenger Lifts with Pit Controller

**Subject :** MRLi Pit Kite Switch Cable Guide Bracket

**Status :** Safety Issue

**Pages :** 1 of 1

---

**Originator :** Stannah Lifts Ltd, Anton Mill, Andover, Hants SP10 2NX 01264 339090

---

Please check that the kite switch cable guide bracket is secured to the guide rail properly without movement on all MRLi Pit Controller Lifts. The dimension given below should be checked and adjust where necessary, under or over-tightening can cause the bracket to fall off during operation of the kite switch cables.

