Stairiser SX




PP and RCD

Technical data sheet for wheelchair platform stairlift

Cable layout for flush wiring

Stannah



1. Please provide the stairlift with a dedicated single phase (including earth) 240v 50Hz permanent electrical supply. This should originate from the appropriate ring main or as a radial circuit connection to the distribution board, terminating in a double pole switched outlet protected by a 10amp fuse. Recommended unit is a crabtree 4827/3 with neon indicator and without cord outlet (or similar manufacture) Please note this is to be wired to the 16th edition IEE Regulations for fixed electrical equipment. Please provide a residual current device (RCD) which automatically disconnects the power supply in the event of an electrical fault.

2. All the wiring is to be chased into the wall by the builder prior to Stannah installing the lift. The position of the junction box and upper and lower surface mounted call stations will be shown on the sales proposal drawing.

Stannah Lifts Ltd. Anton Mill, Andover, Hampshire, SP10 2NX

Tel: 01264 339090 SX 713

Information

sheet

www.stannahlifts.co.uk